







A



B






**A2**



CHECK  
COMPROBAR  
VERIFIER  
ÜBERPRÜFEN




CLEAN PIPES  
LIMPIAR TUBERIAS  
NETTOYER LA TUYAETERIE  
ROHRE SUABER MACHEN




**A4**

X3




X3

A5.



A6.




B1




CHECK  
COMPROBAR  
VERIFIER  
ÜBERPRÜFEN




CLEAN PIPES  
LIMPIAR TUBERIAS  
NETTOYER LA TUYAETERIE  
ROHRE SUABER MACHEN




B2




7




8




9




10




11.



12.



13.



CHECK  
COMPROBAR  
VERIFIER  
ÜBERPRÜFEN



0,5 - 5 Bar  
Max 50 L/min @ 3bar