



A



B



A

B





Diagram illustrating the application of Threadlock to the base of the device. A tube is shown being inserted into the base, and a curved arrow indicates the direction of rotation. A separate curved arrow indicates the direction of rotation for the base. A tube labeled "Threadlock" is shown applying the product to the base.

A3




A4




CHECK
COMPROBAR
VERIFIER
ÜBERPRÜFEN




CLEAN PIPES
LIMPIAR TUBERIAS
NETTOYER LA TUYAERIE
ROHRE SUABER MACHEN




A5




A5




A6




A7



A8



B3




B4




CHECK
COMPROBAR
VERIFIER
ÜBERPRÜFEN




CLEAN PIPES
LIMPIAR TUBERIAS
NETTOYER LA TUYAETERIE
ROHRE SUABER MACHEN




B5



B6



9




CHECK
COMPROBAR
VERIFIER
ÜBERPRÜFEN




1 - 5 Bar

Max 32 L/min @ 3 Bar


1




2



3



4



5

